



Short operation manual for the PartsManager in the Uhlmann E-Shop

For the fastest way to your spare part.

Content

Content	2
Introduction	3
Operator interface	4
From the overview level to the part level.....	6
Adding parts to the shopping basket.....	7
Search function	9
Contact address	10

Introduction


The use of our E-Shop is straightforward thanks to its clear and functional structure. The requested parts can be identified and ordered in different ways, e.g. by using the article number or the article name.

The electronic Uhlmann PartsManager offers another possibility of identifying and ordering spare parts: Just click on the desired part in the exploded view and the part will be identified and added to the shopping basket, together with all the necessary information. The PartsManager is programmed specifically for the customer's machines and integrated into the E-Shop. This service is available for an additional charge.

This manual includes also some links to other documents and to the E-Shop. These links are bold-printed and highlighted in orange colour.

At the end of the document, you will find contact information. If you have any questions, please contact us.

Operator interface



The function of the individual buttons will be listed below:



Show and hide

A click on the double arrow will show or hide the selection window. The desired picture or drawing section can be scaled up or down infinitely using the zoom cursor and shifted by means of the red-framed rectangle.



Scale up or down

Click on the minus or the plus symbol to scale up or down drawing details.



Select drawing section

Place the cursor on the drawing and drag a rectangle with the left mouse button. The section is automatically scaled up when releasing the rectangle.



Scaling drawing to window width

The drawing is positioned in the center and a full view of the drawing appears.



Overview

Jumps to the overview drawing of the machine (see screenshot above).



One level up

Jumps to the next higher level in the module hierarchy, if available.



Previous/next picture of module

These two arrows are used for paging between several drawings of a module.

**Additional information**

Provides additional information that is not contained in the parts list.

**Tree diagram**

Shows or hides the tree diagram on the left.

**Parts list at bottom**

Shows the parts list in the bottom section.

**Parts list on the right**

Shows the parts list in the right-hand section.

**Page overview**

Gives an overview of all available drawing pages.

**Show parts of current drawing only**

Shows the parts belonging to the currently selected drawing.

Each button has a light or dark background. A dark background means that you can activate the respective function by clicking on the button. A light background means that the button cannot be selected at the current level and that the function is therefore not available.

Example:




→ Dark background, i.e. the function is available.



→ Light background, i.e. the function is not available.

From the overview level to the part level

The basic layout of the start window is as follows: the catalog structure (module structure) is displayed on the left-hand side in the form of the tree diagram. The overview drawing of the selected machine is displayed on the right-hand side and the parts list for the selected module is shown at the bottom.



The screenshot shows the software interface with the following components:

- Transaction in Process | ContinueShopping** (top navigation)
- My Details | Log off** (top right navigation)
- Catalogue of parts** (left sidebar)
- Catalog structure** (tree diagram on the left, with a circled 2 next to the 'Module SUPPLEMENTARY PARTS ()' entry)
- Module SUPPLEMENTARY PARTS ()** (selected module, Page 1 from 1)
- Machine overview** (central 3D cutaway diagram of the machine with numbered callouts 1-64, where callout 1 is circled in orange)
- Parts list** (table at the bottom right)

Order	Pos.	Part No.	Description	Quant.	Unit
<input checked="" type="checkbox"/>	1	916211	HEXAGON SOCKET SCREW PLUG R3/4	1	ST
<input type="checkbox"/>	4	900134	CYLINDER HEAD SCREW M6x20	4	ST

To access the part level, there are two possibilities:

- Click on the numbers framed orange ① in the machine overview. The next level opens automatically.
- Click on the plus symbol ② in the tree diagram to access the level of the sub-modules and the individual parts.

Transaction in Process | ContinueShopping My Details Log off

Catalogue of parts Search

1234567; Equip.Nr.: 1234

- MAIN DRIVE, SINGLE STROKE
- FORMING FILM REEL SUPPORT
- CUTTING AND SPLICING TABLE
 - Module BASIC ASSEMBLY ()
- FORMING FILM UNWIND
- HEATING STATION
- FORMING STATION
- INDEX AFTER FORMING
- FOIL REVERSING - FILL SECTION
- VIBRATORY CHUTE
- VIBRATORY FEEDER
- LID FOIL REEL SUPPORT
- SAFETY FLAP
- PRINT REGISTRATION
- SEALING STATION
- SINGLE-STROKE INDEX
- PERFORATING / EMBOSsing STATION
- MULTIPLE STROKE INDEX
- FOIL REVERSING - COMPACT STATION
- COMPACT STATION

Module BASIC ASSEMBLY ()
Page 1 from 1

Adding parts to the shopping basket

Check the checkbox to select a part.

Transaction in Process | ContinueShopping My Details Log off

Catalogue of parts Search


1234567; Equip.Nr.: 1234

- MAIN DRIVE, SINGLE STROKE
- FORMING FILM REEL SUPPORT
- CUTTING AND SPLICING TABLE
- FORMING FILM UNWIND
- HEATING STATION
- FORMING STATION
 - Module BASIC ASSEMBLY ()
 - Module SUPPLEMENTARY PARTS ()
- Module PRESSURE BOX 16KN ()
- Module DRIVE PARTS ()
- Module CAM PVC ()
- Module CAM ALU ()
- Module SCANNING ()
- Module PLUG ASSIST ()
- Module CAM ()
- Module DRIVE PARTS ()
- Module ROLLER DRIVE ()
- INDEX AFTER FORMING
- FOIL REVERSING - FILL SECTION
- VIBRATORY CHUTE
- VIBRATORY FEEDER
- LID FOIL REEL SUPPORT
- SAFETY FLAP
- PRINT REGISTRATION
- SEALING STATION
- SINGLE-STROKE INDEX
- PERFORATING / EMBOSsing STATION
- MULTIPLE STROKE INDEX

Module SUPPLEMENTARY PARTS ()
Page 1 from 1

Order	Pos.	Part No.	Description	Quant.	Unit
<input checked="" type="checkbox"/>	1	916211	HEXAGON SOCKET SCREW PLUG R3/4	1	ST
<input type="checkbox"/>	4	900134	CYLINDER HEAD SCREW M6x20	4	ST

Click on “Add to Shopping basket”.



Order	Pos.	Part No.	Description
<input checked="" type="checkbox"/> 1	10	916211	HEXAGON SOCKET SCREW P
<input type="checkbox"/> 4	20	900134	CYLINDER HEAD SCREW M6:

Add to Shoppingbasket

Go directly to the shopping basket over “1 Item(s) to the value of 0 EUR”.



1 Item(s) to the value of 0 EUR ContinueShopping

Catalogue of parts Search

1234567; Equip.Nr.: 1234


- MAIN DRIVE, SINGLE STROKE
- FORMING FILM REEL SUPPORT
- CUTTING AND SPLICING TABLE
- FORMING FILM UNWIND
- HEATING STATION

Module SUPPLEMENTARY PARTS
Page 1 from 1

Here, you can request quotations or order parts as usual (see E-Shop manual).

Search function


Click on "Search".



Search criteria:

If the search field names are marked with "*", the search terms are automatically provided with wildcard characters at the beginning and at the end. The asterisk "*" can also be used as wildcard character for several characters within the search term. For example, if you search for "Forming film reel support", just enter "Forming film*" into the search field. The search terms are not case-sensitive. Search terms that are entered into several fields are ANDed together.

If you want to limit the search to a certain module, select "Search in" and then "Change" and finally the desired module. Enter the search term and start the search.



Contact address

E-Mail Hotline: shophotline@uhlmann.de

Uhlmann Pac-Systeme GmbH & Co. KG

i.V. Reinhold Jeggle
Spare Parts Manager
Customer Support & Services

Uhlmannstr. 14-18
88471 Laupheim
Germany

Phone + 49 (0)7392 702-8281
Fax + 49 (0)7392 702-1281

jeggle.r@uhlmann.de
www.uhlmann.de